

Attachment A: Digital Images

Page 1 of 4

July 23rd, 2008

BOE Building 22nd Floor East Clearance
Sacramento, CA



- 1) Image of ambient air sampling location at front entry of BOE Building (Subject Building) located at 450 N Street, Sacramento, California at time of assessment.



- 2) Image of air sampling activity (outside containment) within hallway leading to 22 East containment entry area at time of assessment.



3) Image of posting upon entry into 22 Eastern containment system at time of assessment.



4) Image of air sampling equipment within 22 East containment area at northeastern corner at time of assessment.



- 5) Image within 22nd Floor east containment area indicating location of air sampling equipment and extent of perimeter and interior wall removal.



- 6) Additional image of air sampling location within interior of 22 East containment area at time of assessment.



7) Close-up image of air sampling equipment and perimeter wallboard removal during clearance assessment within 22 East containment area.



8) Image of ambient air sampling equipment located on northern portion of 23rd floor area.